



28615

Stöd sitsrör Cross 6
Support seat tube Cross 6
Stütze Sitzrohr Cross 6

1a16628.1 2020-04-22




1



Loctite 243

2





3



T30



10Nm



Etac Supply Center AB
Långgatan 12
SE-334 33 Anderstorp
www.etac.com