




8020 9509



Bålstöd
Trunk support
Seitenpelotten




x2




x1

78527.8 2024-10-01


1.



2.




3.




Clean

4.



Swift Mobil-2, Alto

4.




Etac Supply Center AB
Långgatan 12
SE-334 33 Anderstorp
www.etac.com




Vid tvätt: se till att alla kardborreytor är sammanfogade.
For washing: make sure all Velcro surfaces are joined together.
Zum Waschen: Stellen Sie sicher, dass alle Klettverschlüsse fest miteinander verbunden sind!

Clean


5.



6.




7.




Swift Mobil-2, Alto

5.



6.



7.

