



1x




1x

Storage and Transport	50°C	90%	1060 hPa
	-10°C	20%	800 hPa
Operating	40°C	90%	1060 hPa
	5°C	20%	800 hPa

DUTY CYCLE: 10% MAX 2 min./18 min.




1.




2.

13 mm 6 mm



3.

13 mm 6 mm



4.

2×

6×


1×

5.




6.





13 mm 6 mm




7.

13 mm 6 mm




8.  **13 mm**  **6 mm**

9.  **4 mm**

10.  **13 mm**  **6 mm**

11.  **13 mm**  **6 mm**


12.




13.


8 mm & ⊕




14.




15.



16.




17.




18.


8 mm & ⊕




19.



20.



21.

**C**

Storage and Transport	50°C	90%	1060 hPa
	-10°C	20%	800 hPa
Operating	40°C	90%	1060 hPa
	5°C	20%	800 hPa

DUTY CYCLE: 10% MAX 2 min./18 min.

D

22.

